




MANGUITO ELECTROSOLDABLE SIN TOPE  
PE100 SDR11 MOP10(GAS) MOP16(AGUA)

	MEDIDA	REFERENCIA
	20	AP0000612660
	25	AP0000612661
	32	AP0000612662
	40	AP0000612663
	50	AP0000612664
	63	AP0000612665
	90	AP0000612667
	110	AP0000612668
	160	AP0000612671
	200	AP0000612673
	250	AP0000612675
	315	AP0000612670


MANGUITO DE CIERRE ELECTROSOLDABLE (CAP)  
PE100 SDR11 MOP10(GAS) MOP16(AGUA)

	MEDIDA	REFERENCIA
	20	AP0000612025
	25	AP0000612026
	32	AP0000612027
	40	AP0000612028
	50	AP0000612029
	63	AP0000612030
	90	AP0000612032
	110	AP0000612033
	160	AP0000612035


CODOS 45° ELECTROSOLDABLES  
PE100 SDR11 MOP10(GAS) MOP16(AGUA)

	MEDIDA	REFERENCIA
	32	AP0000612092
	40	AP0000612094
	50	AP0000612096
	63	AP0000612098
	90	AP0000612102
	110	AP0000612104
	160	AP0000615275


CODOS 90° ELECTROSOLDABLES  
PE100 SDR11 MOP10(GAS) MOP16(AGUA)

	MEDIDA	REFERENCIA
	20	AP0000612090
	25	AP0000612091
	32	AP0000612093
	40	AP0000612095
	50	AP0000612097
	63	AP0000612099
	90	AP0000612103
	110	AP0000612105
	160	AP0000615276


CODOS 30° ELECTROSOLDABLES  
PE100 SDR11 MOP10(GAS) MOP16(AGUA)

	MEDIDA	REFERENCIA
	90	AP0000615272
	110	AP0000615273
	160	AP0000615340


TE KIT ELECTROSOLDABLE (CON MANGUITO)  
PE100 SDR11 MOP10(GAS) MOP16(AGUA)

	MEDIDA	REFERENCIA
	20*	AP0000136580
	32	AP0000612161
	40	AP0000612162
	50	AP0000612163
	63	AP0000612164
(*) : Sin manguito		


TE ELECTROSOLDABLE  
PE100 SDR11 MOP10(GAS) MOP16(AGUA)

	MEDIDA	REFERENCIA
	25	AP0000612160
	90	AP0000612166
	110	AP0000612167
	160	AP0000612277
	180	AP0000615691
	225	AP0000615692


REDUCCION ELECTROSOLDABLE  
PE100 SDR11 MOP10(GAS) MOP16(AGUA)

	MEDIDA		REFERENCIA
		32	20
	32	25	AP0000615502
	40	20	AP0000615387
	40	32	AP0000615388
	50	20	AP0000612069
	50	32	AP0000612070
	50	40	AP0000612071
	63	32	AP0000615389
	63	40	AP0000615390
	63	50	AP0000612072
	90	50	AP0000615391
	90	63	AP0000615392
	110	63	AP0000615393
	110	90	AP0000615693
	160	110	AP0000615695

DERIVACION TOMA EN CARGA  
CON MANGUITO O REDUCCION (MARCADAS CON \*)  
PE100 SDR11 MOP10(GAS) MOP16(AGUA)

	MEDIDA		REFERENCIA
		63	32
	90	20*	AP0000615653
	90	25*	AP0000615654
	90	32	AP0000615655
	90	40*	AP0000615656
	110	20*	AP0000615659
	110	25*	AP0000615660
	110	32	AP0000615661
	110	40*	AP0000615662
	110	50*	AP0000615663
	160	20*	AP0000615672
	160	25*	AP0000615673
	160	32	AP0000615674
	160	40*	AP0000615675


DERIVACION TOMA EN CARGA  
SIN MANGUITO  
PE100 SDR11 MOP10(GAS) MOP16(AGUA)

	MEDIDA		REFERENCIA
		40	20
	40	32	AIMTU040X032
	50	25	AP0000612702
	50	32	AP0000615080
	63	20	AP0000612631
	63	25	AP0000612633
	63	32	AP0000612632
	63	40	AP0000612623
	90	32	AP0000612634
	90	50	AP0000612636
	90	63	AP0000612701
	110	32	AP0000612637
	110	63	AP0000612624
	160	32	AP0000612641
	160	50	AP0000612642
	160	63	AP0000612650


TOMA SIMPLE  
PE100 SDR11 MOP10(GAS) MOP16(AGUA)

	MEDIDA		REFERENCIA
		40	20
	63	20	AP006126320K
	63	32	AP0000612757
	90	32	AP0000615285
	90	63	AP0000612819
	110	32	AP0000615334
	110	50	AP0000615031
	110	63	AP0000612760
	110	90	AP0000615411
	160	32	AP0000612886
	160	63	AP0000612762
	160	90	AP0000615413
	160	110	AP0000615739


VALVULA DE ESFERA ¼ VUELTA KHP EN PE-AD  
PE100 SDR11 MOP10 (GAS) MOP16(AGUA)

	MEDIDA	REFERENCIA
		32
	40	AP0000612497
	63	AP0000612494
	90	AP0000612495
	160	AP0000612483


TRANSICION MANGUITO UNION PE-AC ROSCA MACHO  
PE100 SDR11 **MOP5 (GAS)**

	MEDIDA		REFERENCIA
	20	1/2"	AP0000612578
	32	1"	AP0000612580
	40	1 1/4"	AP0000612582
	50	1 1/2"	AP0000612584
	63	2"	AP0000612586


TRANSICION MANGUITO UNION PE-AC ROSCA MACHO  
PE100 SDR11 **MOP16 (AGUA)**

	MEDIDA		REFERENCIA
	20	1/2"	AP0000612710
	32	1"	AP0000612712
	40	1 1/4"	AP0000612713
	50	1 1/2"	AP0000612714
	63	2"	AP0000612715


TRANSICION MANGUITO UNION PE-AC ROSCA HEMBRA  
PE100 SDR11 **MOP5 (GAS)**

	MEDIDA		REFERENCIA
	32	1"	AP0000612570
	40	1"	AP0000612571
	40	1 1/4"	AP0000612572
	50	1 1/2"	AP0000612574
	63	2"	AP0000612576


TRANSICION MANGUITO UNION PE-FUNDICION  
ROSCA HEMBRA  
PE100 SDR11 **MOP16 (AGUA)**

	MEDIDA		REFERENCIA
	32	1"	AP0000612595
	40	1 1/4"	AP0000612596
	50	1 1/2"	AP0000612692
	63	1 1/2"	AP0000612708
	63	2"	AP0000612693


TRANSICION CODO UNION PE-AC ROSCA MACHO  
PE100 SDR11 **MOP5 (GAS)**

	MEDIDA		REFERENCIA
	40	1 1/4"	AP0000612602
	50	1 1/2"	AP0000612604
	63	2"	AP0000612606


TRANSICION CODO UNION PE-ACERO ROSCA MACHO  
PE100 SDR11 **MOP16 (AGUA)**

	MEDIDA		REFERENCIA
	40	1 1/4"	AP0000612122
	50	1 1/2"	AP0000612124
	63	2"	AP0000612126


TRANSICION CODO UNION PE-AC ROSCA HEMBRA  
PE100 SDR11 **MOP5 (GAS)**

	MEDIDA		REFERENCIA
	32	1"	AP0000612610
	40	1"	AP0000612611
	40	1 1/4"	AP0000612612
	50	1 1/2"	AP0000612614
	63	2"	AP0000612616

TRANSICION PE-AC SOLDAR CON MANGUITO INCLUIDO  
PE100 SDR11 **MOP10 (GAS)**

	MEDIDA		REFERENCIA
	32	1"	AP0000612780
	40	1 1/4"	AP0000612781
	63	2"	AP0000612783
	90	3"	AP0000612784
	160	6"	AP0000612787

TRANSICION PE-AC SOLDAR CON MANGUITO  
PE100 SDR11 **MOP10 (GAS)**

	MEDIDA		REFERENCIA
	32	1"	AP0000615475
	40	1 1/4"	AP0000615476
	50	1 1/2"	AP0000615477
	63	2"	AP0000615478

**DISPONEMOS DE ACCESORIO PARA SOLDAR A TOPE**  
**COLSULTAR LISTA DE PRECIOS**